

Panasonic Out of Warranty conditions 2014

PRICING STRUCTURE

The complete repair cost consist of:

- Basis rate (as mentioned in the price list / model overview)
- a Cash on Delivery (COD) [fee about 15,50 Euro per unit / shipment](#)
- transport cost of 10,00 Euro / shipment

Basis rate repair price + COD fee + transport cost = complete repair cost (net cost)

WARRANTY CONDITION:

1 year warranty on the replaced part(s) and the related repair work.

NOTE AND EXCEPTIONS:

Unit should send to the service center in an appropriate packing style and carton box .

Those fixed prices are only valid for normal defects.

The basis prices will not cover repairs on units received with hidden damages like,

- > liquid inside the component
- > damaged printed circuit boards (PCB),
- > units were a third party made any changes on the product itself
and components with transport damages or fallen down.

For components where the above exceptions apply, a chargeable individual cost estimation could be created upon request.

CONTACT DETAILS:

toyota.panasonic@transerv2000.de

**TRANSERV 2000 GmbH
Panasonic Service Shop
Robert-Bosch Strasse 33 a
64625 Bensheim
Germany
Tel. +49 6251 985600
Fax +49 6251 9856060**

Revised Pricing Structure By Audio Product Type (Year 2014)
Out Of Warranty Repair

Position	Audio Product Type	Base rate (net cost) for 2014 excl. 15,50 Euro COD fee and 13,50 Euro logistic cost
1	Display Ass'y / Multi Display Ass'y	54,40
2	Amplifier Standard Type	61,00
3	Radio with Cassetteplayer	79,50
4	Radio with CD Player, Category 1	87,70
	Amplifier	
5	Radio with CD Player, Category 2	104,90
6	6 Disc CD Changer (Magazin Type, Trunk installation)	113,40
7	Display (Center)	115,00
8	Radio with CD player, Category 3,	122,50
	Radio with CD- and Cassette- Player	
9	6 Disc CD Changer Indash Type	146,30
10	Radio with CD Player, Category 4	154,80
11	Radio with 6 Disc CD Changer	171,40
	Display Audio (Toyota Touch)	
12	Mini Disc Changer	201,60
13	TFT Monitor	259,10
	Rear Seat Entertainment Unit; Category 1	
14	DVD Player	315,40
	Smartphone display audio	
15	Rear Seat Entertainment Unit, Category 2	468,00
16	Blu Ray Player	735,00
17	Cost estimation option 2 UNREPAIRED unit back to sender	30,00

EXCEPTION

Position	Audio Product Type	FIXED AMOUNT (in Euro)
A	Avensis Multi Display Ass'y 86110-05020	59,95

Explanation

C.O.D. = Cash On Delivery

TOYOTA AUDIO MODEL OVERVIEW BY PRODUCT TYPE AND REPAIR PRICE

SPECIAL CASE: Fixed amount 59,95 Euro		
Toyota Part Number	Panasonic Part Number	Audio Product type
86110-05020	CN-TS6270LC	Multi Display assy Avenis

Position 1: Base rate 54,40 Euro + COD fee and logistic cost			
Toyota Part Number	Panasonic Part Number	Audio Product type	
86110-0D030	CN-TS0372LC	Display ass'y	
86110-0D040	CN-TS0370LC		
86110-52130	CN-TS0373A		
86110-52140	CN-TS0371A		
86111-52030	CN-TS0272B		
86110-52121	CN-TS0270A		
86110-52111	CN-TS0272A		
86111-52040	CN-TS0270B		
86110-05010	CN-TS6070L		Multi Display assy
86110-05011	CN-TS6070LAC		

Position 2: Base rate 61,00 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
86280-60230	CY-BT4001A	Amplifier (Standard Type)
86280-60240	CY-BT4070A	

Position 3: Base rate: 79,50 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
08600-00880	CQ-LS0520F	Radio with Cassetteplayer
08600-00887	CQ-SS0620F	
08600-00888	CQ-YS0620F	
08600-00889	CQ-YS0621F	
08600-00917	CQ-SS0720F	
08600-00918	CQ-YS0720F	
08600-00932	CQ-SS0920F	
08600-00934	CQ-YS0920F	
08600-00956	CQ-SS0070F	
08600-00963	CQ-YS0170F	
08600-00964	CQ-YS0171F	
86100-60080	CQ-YT4620A	
86120-02250	CQ-TS7171L	

Position 4: Base rate 87,70 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
08600-00896	CQ-JS0620F	Radio with CD Player, Category 1
08600-00935	CQ-JS0921F	
08600-02840	CQ-MS7920F	
08600-05820	CQ-MS6070F	
08600-52830	CQ-MS0170F	
08600-52831	CQ-MS0370F	
08600-52832	CQ-MS0270F	
86120-02190	CQ-MS7920L	
86120-05060	CQ-MS6070L	
86120-05140	CQ-JS6871G	
86120-0D030	CQ-MS0170L	
86120-0D140	CQ-MS0370L	
86120-0F050	CQ-JS7871G	
86120-0H010	CQ-MS0570LC	
86120-12A30	CQ-JS7671A	
86120-12B00	CQ-JS7670A	
86120-12D40	CQ-JS7073AJ	
86120-13050	CQ-TS1717A	
86120-1A130	CQ-MS7920A	
86120-1A170	CQ-TS1737A	
86120-42270	CQ-JT3870AJ	
86120-52030	CQ-MS0820A	
86120-52260	CQ-MS0270A	
86120-52390	CQ-MS0371AK	
86120-74010-E0	CQ-JS0970AD	
86120-74010-A0	CQ-JS00F64D	
86120-74010-C0	CQ-JS00F84D	
86120-74010	CQ-JS0870AD	
86120-12D50	CQ-JS7077AJ	
86120-05180	CQ-JS6073G	
86120-05141	CQ-JS6071G	
86120-02B80	CQ-JS7079G	
86120-0F080	CQ-JS7071G	
86120-02B70	CQ-JS7075G	
86120-0D640	CQ-JS01F1AE	
86120-0D650	CQ-JS01F2AE	
86120-0D660	CQ-JS01F3AE	
86120-0D670	CQ-JS01F4AE	
86120-05220	CQ-JS61F0AE	
86120-05210	CQ-JS61F1AE	
86120-02880	CQ-JS72F0AE	
86120-0F140	CQ-JS73F1AE	
86120-12F40	CQ-JS72F14D	
86280-60230	CY-BT4001A	Amplifier
86280-60240	CY-BT4070A	

TOYOTA AUDIO MODEL OVERVIEW BY PRODUCT TYPE AND REPAIR PRICE

Position 5: Base rate 104,90 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
08600-00919	CQ-JS0720F	Radio with CD Player, Category 2
08600-00936	CQ-JS0920F	
08600-00965	CQ-JS0170F	
08600-00966	CQ-JS0171F	
86120-02260	CQ-TS7170L	
86120-02380	CQ-TS7471LC	
86120-02460	CQ-TS7473LC	
86120-02580	CQ-JS7771G	
86120-02690	CQ-JS7770G	
86120-05110	CQ-TS6670G	
86120-05111	CQ-TS6670GA	
86120-05120	CQ-TS6671G	
86120-05121	CQ-TS6671GA	
86120-0D210	CQ-TS0570LC	
86120-0D211	CQ-TS0570G	
86120-0F010	CQ-TS7421LC	
86120-0F030	CQ-JS7772G	
86120-12880	CQ-TS7471A	
86120-13060	CQ-TS7170A	
86120-1A180	CQ-TS7172A	
86120-42140	CQ-TT3570A	
86120-42141	CQ-JT3871AJ	
86120-47110	CQ-MS0370A	
86120-47220	CQ-JT0570A	
86120-47280	CQ-MS0570A	
86120-47281	CQ-JS0873AJ	
86120-52480	CQ-TS0570A	
86120-52481	CQ-JS0871AJ	
86120-52810	CQ-TS0670A	
86120-52811	CQ-JS0872AJ	
86120-02F70	CQ-JS73F6AE	
86120-02G00	CQ-JS73F7AE	

Position 6: Base rate 113,40 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
08601-00862	CX-CS0620F	6 Disc CD Changer Magazin Type Trunk Installation
08601-00879	CX-CS0720F	
08601-00910	CX-CS0721F	
08601-00911	CX-CS0722F	
08601-00912	CX-CS0723F	
86270-48040	CX-CT8000A	

Position 7: Base rate 115,00 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
86110-30430	CV-VT53F2AJ	Display Center
86110-30420	CV-VT53F3AJ	
86111-76030	CV-TS02J0JT	

Position 8: Base rate 122,50 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
86120-02A70	CQ-JS7971G	Radio with CD Player, Category 3
86120-12C70	CQ-JS7970AJ	
86120-02F50	CQ-JS70F0G	
86120-05150	CQ-JS6870G	
86120-05151	CQ-JS6070G	
86120-0F060	CQ-JS7870G	
86120-0F070	CQ-ES7870G	
86120-0F090	CQ-JS7070G	
86120-47221	CQ-JS0874AJ	
86120-02C00	CQ-JS7078G	
86120-05190	CQ-JS6072G	
86120-52B00	CQ-JS00F4AD	
86120-1A190	86120-1A190-EX	
86120-02F80	CQ-JS73F8AE	
86120-02G10	CQ-JS73F9AE	
86120-05070	CQ-MS6270L	
86120-05071	CQ-MS6570LC	
86120-05080	CQ-MS6271L	
86120-05081	CQ-MS6571LC	
86120-47120	CQ-ES0370A	
08600-05822	CQ-MS6271F	
08600-05821	CQ-MS6270F	

TOYOTA AUDIO MODEL OVERVIEW BY PRODUCT TYPE AND REPAIR PRICE

Position 9: Base rate 146,30 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
08601-00892	CX-CS0820F	6 Disc CD Changer In-Dash 1 DIN Type
08601-00907	CX-CS0820FA	
08601-00913	CX-CS0171F	
08601-00914	CX-CS0170F	
08601-00932	CX-CS0820FB	

Position 10: Base rate 154,80 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
08600-00945	CQ-TS0920F	Radio with CD Player, Category 4
08600-00949	CQ-TS0920FA	
08600-00955	CQ-TT3070F	
08600-00958	CQ-TS0920FB	
08600-00959	CQ-TT3070FA	
08600-01001	CQ-TT3370F	
08600-01002	CQ-TT5370F	
86120-05130	CQ-TS6672G	
86120-05131	CQ-TS6672GA	
86120-28380	CQ-TS0920A	
86120-28381	CQ-TS0920AA	
86120-28382	CQ-TS0920AB	
86120-28470	CQ-TS0370A	
86120-42060	CQ-TT3070A	
86120-42061	CQ-TT3070AA	
86120-42130	CQ-TT3370A	
86120-44080	CQ-TT5170A	
86120-44170	CQ-TT5370A	
86120-12D80	CQ-JS7076AJ	
86120-76170	CQ-JS00F1AJ	
86120-76140	CQ-JS00F0AJ	
86120-42400	CQ-JT32F2AJ	
86120-42460	CQ-JT32F3AJ	

Position 11: Base rate 171,40 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
86120-02390	CQ-TS7470LC	Radio with 6 Disc CD Changer
86120-02470	CQ-TS7472LC	
86120-02700	CQ-ES7770G	
86120-05160	CQ-ES6870G	
86120-0F020	CQ-TS7420LC	
86120-0F040	CQ-ES7772G	
86120-12B10	CQ-ES7670A	
86120-42220	CQ-TT3571A	
86120-42221	CQ-ET3872AJ	
86120-42280	CQ-ET3870AJ	
86120-05161	CQ-ES6070G	
86120-0F100	CQ-ES7070G	

Position 11 (continuation): Base rate 171,40 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
86140-05010	CV-VS61F0AE	Display Audio (Toyota Touch)
86140-05020	CV-VS61F1AE	
86140-05030	CV-VS61F2AE	
86140-05040	CV-VS61F3AE	
86140-02090	CV-VS01F6AE	
86140-02100	CV-VS01F7AE	
86140-0F010	CV-VS71F0AE	
86140-0W010	CV-VT31F0CE	
PZ473-00213-00	CV-VS02FCCE	
86140-47140	CV-VS02F94D	
86140-47160	CV-VS02FB4D	
86140-47150	CV-VS02F84D	
86140-47170	CV-VS02FA4D	
86140-47110	CV-VS01F24D	
86140-47100	CV-VS01F34D	
86140-47080	CV-VS01F14D	
86140-47090	CV-VS01F04D	
86140-0K130	CV-VT01F5TT	
86140-0K130	CV-VT01F0TT	
86140-0K120	CV-VT01F3TT	
86140-02040	CV-VS02F0AE	
86140-02020	CV-VS02F1AE	
86140-02030	CV-VS02F2AE	
86140-02010	CV-VS02F3AE	
86140-0F020	CV-VS72F0AE	
86140-0F030	CV-VS72F1AE	
86140-05050	CV-VS62F0AE	
86140-05060	CV-VS62F1AE	
86140-05070	CV-VS62F2AE	
86140-05080	CV-VS62F3AE	
86140-42070	CV-VT32F04D	
86140-42040	CV-VT32F14D	
86140-42100	CV-VT32F24D	
86140-42090	CV-VT32F34D	
86140-02080	CV-VS73F0AE	
86140-02130	CV-VS73F1AE	

Position 12: Base rate 201,60 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
08601-00900	CX-ES0920F	Mini Disc Changer
08601-00901	CX-ES0921F	

TOYOTA AUDIO MODEL OVERVIEW BY PRODUCT TYPE AND REPAIR PRICE

Position 13: Base rate 259,10 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
86111-20010	CN-TS6271A	TFT Monitor and Rear seat entertainment unit, Category 1
86111-20030	CN-TS6670A	
86111-53030	CN-TS6190A	
86680-48081	CV-RS5990AJ	
86111-76020	CV-TS00J0AJ	
86680-60190-AX	CV-RT41G0AJ	
86680-60190-BX	CV-RT41G1AJ	

Position 15: Base rate 468,00 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
86680-60030-A0	CV-RT4972AJ	Rear Seat Entertainment Unit, Category 2
86680-60030-B0	CV-RT4973AJ	
86680-50150-A1	CV-RS5961AJ	
86680-50150-A0	CV-RS5963AJ	
86680-50120-A1	CV-RS5964AJ	
86680-50120-B0	CV-RS5965AJ	
86680-50120-A0	CV-RS5966AJ	
86680-50180	CV-RS5960AJ	
86680-50260-A1	CV-RS52E3AJ	
86680-50260-B0	CV-RS52E4AJ	
86680-50260-A0	CV-RS52E5AJ	

Position 14: Base rate 315,40 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
08601-00916	CX-ZS0270F	DVD Player
86270-50190	CX-VS5670A	
86270-50260	CX-VS5970AJ	
86270-50330	CX-VS5971AJ	
86140-74010	CV-VS01F5JT	Smartphone display audio

Position 16: Base rate 735,00 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
86270-50740	CX-BSS1F0AJ	Blu ray player
86270-50550	CX-BSS1F1AJ	

Position 17: Base rate 30,00 Euro + COD fee and logistic cost		
Toyota Part Number	Panasonic Part Number	Audio Product type
Cost estimation option 2 UNREPAIRED unit back to sender		All models

PRICE STRUCTURE

Cash on delivery fee (COD) = 15,50 Euro

Logistic cost = 13,50 Euro

Example: Repair price unit (Pos.8) Radio w. CD Player category 3 + COD fee + Logistic cost = Repair net price

122,50 Euro + 15,50 Euro + 13,50 Euro = 151,50 Euro (net price)

EXCEPTION

Only 86110-05020 Avensis multi display assy are not follow the general price structure.

This multi display is available for fixed amount of 59,95 Euro, including all cost, supplied on COD base.

WARRANTY CONDITION:..

1 year warranty on the replaced part(s) and the related repair work.

NOTE AND EXCEPTIONS:..

Unit should send to the service center in an appropriate packing style and carton box .

Those fixed prices are only valid for normal defects.

The flat prices will not cover repairs on units received with hidden damages like,

- > liquid inside the component
- > damaged printed circuit boards (PCB),
- > units were a third party made any changes on the product itself

and components with transport damages or fallen down.

PROCESS FLOW

- 1) Service center receives out of warranty unit for analysis and repair.
- 2) After analysis of the unit, a cost estimation will be generated (repair price according to the current pricelist + logistic cost + COD fee = repair net price)
- 3) One of the 3 options could be choosen: a) Repair unit for announced repair net price,
 - b) Unrepaired unit back to sender for 30,00 Euro + logistic cost + COD fee = Unrepaired return unit net price
 - c) Scrap defect unit at service center for free of charge
- 4) Customer should decide for further processing within the next 10 working days, by return of signed cost estimation document.
- 5) Following customers decision on the cost estimation document, Service center will continue the process accordingly.